



## 429997 TG

Art. No.	Art. Name
429997 TG	OIL FILTER L/C URJ201 12/20 1UR/3UR/1VD

### Comparison Number(s)

Suitable to replace	Reference(s)
Lexus	04152-YZZA4   04152-38020
Toyota	04152-YZZA4   04152-38020

Used in vehicles: LEXUS

Model	Submodel
LX III AWD 2007 -	LX 450d 4.5 VVTi 32V - 200kW / 272hp
LX III AWD 2007 -	LX 570 5.7 32V - 270kW / 367hp
LX III AWD 2007 -	LX 570 5.7 32V - 282kW / 383hp
LX III AWD 2007 -	LX 570 5.7 32V - 285kW / 387hp

Used in vehicles: TOYOTA

Model	Submodel	Model	Submodel
Land Cruiser 200 4x4 (J20) 2007 -	(URJ200)	Land Cruiser 200 4x4 (J20) 2007 -	(VDJ200)
Land Cruiser 200 4x4 (J20) 2007 -	(URJ200)	Land Cruiser 200 4x4 (J20) 2007 -	(VDJ200)
Land Cruiser 200 4x4 (J20) 2007 -	(URJ200)	Land Cruiser V8 4x4 (J20) 2012 -	(URJ202)
Land Cruiser 200 4x4 (J20) 2007 -	(URJ200)	Sequoia II 4x4 2000 - 2022	(USK65)
Land Cruiser 200 4x4 (J20) 2007 -	(URJ202)	Sequoia II 4x4 2000 - 2022	(USK65)
Land Cruiser 200 4x4 (J20) 2007 -	(URJ202)	Tundra II 2006 - 2021	(USK50)
Land Cruiser 200 4x4 (J20) 2007 -	(URJ202)	Tundra II 2006 - 2021	(USK51)
Land Cruiser 200 4x4 (J20) 2007 -	(VDJ200)	Tundra II 4x4 2002 - 2021	(USK50)
Land Cruiser 200 4x4 (J20) 2007 -	(VDJ200)	Tundra II 4x4 2002 - 2021	(USK55)
Land Cruiser 200 4x4 (J20) 2007 -	(VDJ200)	Tundra II 4x4 2002 - 2021	(USK56)
Land Cruiser 200 4x4 (J20) 2007 -	(VDJ200)	Tundra II 4x4 2002 - 2021	(USK57)
Land Cruiser 200 4x4 (J20) 2007 -	(VDJ200)	Tundra II Crew Cab Pickup 4x4 2006 - 2013	(USK56)